
















Induction Repairs

Prices are subject to change without notice

Issued November 2021

Power Source	Cable Type	Purpose	Color	Replacing	Note	Image	Repair Part Number	Repair Cost	
PROHEAT	Liquid Cooled	Heating Cable	Blue	1-Socket	Per end		REWORK-LIQ-HEAT	\$450	
		Extension Cable	Black	Power Source End			REWORK-LIQ-OUTP	\$575	
			Black	2-pin	Replaces Y & both connectors to keep ends same length		REWOR-LIQ-OUT-Y	\$500	
	Rolling Inductor				Power Source End			RE-RI-OUTP	\$575
					Cable and power source end	Replaces cables, hoses, jacket and molded end.		REWORKHOSEHD30 REWORKHOSEHD60	\$2500 \$4500
					Inductor Coil Only			RE-RI-COILCORE	\$3,125
					Inductor Coil and Sheet Metal			RE-RI-FULLHEAD	\$4,375
	PEOHEAT / ARCREACH HEATER	Air Cooled	Extension Cable	Orange	Power Source End			REWORK-AIR-OUTP	\$500
				Orange	2-sockets	Replaces Y & both connectors to keep ends same length		REWOR-AIR-OUT-Y	\$500
			Heating Blanket	Yellow	2-pins	Replaces both connectors. *Requires 8 inches of usable yellow lead to be exposed.		REWORKBLANKET	\$525
ARCREACH HEATER	Air Cooled	Heating Cable	Orange	1-pin	Per end		RE-AIR-EXTRUDED	\$375	
		Quick Wrap	Orange	1-pin and lug	Replacement cable assembly including power connector, cable, lug, and serial number label (if applicable).		RE-279590	\$1,200	
		TC Extension Cable	Orange	Power Source End	Per end		RE-HARTING	\$600	
		TC Extension Cable	Orange	2-sockets	Repair damage to enclosure and/or power connectors		RE-TCBOX-CONN	\$1,750	
		TC Extension Series Adapter	N/A	2-sockets	Repair damage to enclosure and/or power connectors		RE-SABOX-CONN	\$1,025	

Sheet 1 of 4

Induction Repairs

If a cable is damaged it must be cut off at the damaged area and a shorter cable will be made by installing 1 new end. For longer cables, it may be cut into 2 shorter cable lengths requiring 2 ends to be installed. Sections with severe burns or exposed reinforcing string will be cut off.

Please read the following requirements carefully to avoid additional charges. Costs will be incurred at \$100 per hour if any of the following is incomplete. (\$100 minimum charge)

- 1) Cables need to be in repairable condition. Unrepairable cables will be scrapped or shipped back at the customer expense.
 - a) Air cooled blankets with melted insulation on the interior litz cable are not to be repaired, they should be replaced.
- 2) Clearly mark the location of damage on the cable
- 3) Preheat insulation cover needs to be removed from liquid or air cooled cables.
- 4) Coolant must be removed from liquid-cooled cables prior to shipping and coolant fittings must remain installed.
- 5) The Cable Repair Worksheet must be filled out completely with the following information.
 - a) Serial number of cable(s) being repaired

- b) Approximate length of cable(s) desired after repair
- c) Identify the damage, location, and how it is marked on the cable.
- d) End(s) required for the repair per the table above.

6) Customer information needs to be filled out completely.

Standard lead time for repair is 4 weeks plus shipping time and is dependent on part availability.

Customer Information:

Name of Company: _____

Return Shipping Address: _____

City, State & Zip: _____

Contact Person and Phone: _____

Customer PO #: _____

Special Instructions: _____

Email Address: _____
(Required for Billing):

Preferred Return Shipper: _____
(If applicable)

Customer Shipping Account: _____
(If applicable)

Note: Customer is responsible for shipping costs to and from repair shop

* Invoice will be sent to the customer provided email address. Please verify below your choice of payment method. To pay via Credit Card, a payment request can be submitted via PayPal; An account is NOT needed for this action. Customer can opt to pay as guest once the request has been sent.

*Customer is responsible for any processing fees charged by processor.

- PayPal Check Wire Transfer

Ship Damaged Coils and Cables to:

Specialized Products,
Ltd. Attn: Cable Repair
200 Summer St.
Clintonville, WI 54929

Phone: (715) 823-3727

Repair Worksheet

Line #	Serial #	Description (part type and length)	Repair Description		Repair Part Number	Quantity	Cost	Inspection Fee \$100 Per Hour	Total Repair Cost
				description of approximate length of cable desired, what the damage is, how the damaged area is marked, and work expected to be done)					
Sample	LG-21	3000 foot heating cable about 30 feet and 1 about 20 feet. Needs 2 new ends.		Leak at 30 feet marked with orange paint. Make into 2 cables. 1 cable about 30 feet and 1 about 20 feet. Needs 2 new ends.	REWORK-LIQ-HEAT	2	\$		\$
Sample	MA-XXXXXXG	1950 extension cable		Heat damage at 15 feet. Marked with tape. Y end also has heat damage. Cut and make about 35 foot cable with new power source end and Y end.	REWORK-LIQ-OUTP REWOR-LIQ-OUT-Y	1 1	\$		\$
1	(\$		\$
2							\$		\$
3							\$		\$
4							\$		\$
5							\$		\$
6							\$		\$
7							\$		\$
8							\$		\$
9							\$		\$

Cable Repair Worksheet

Line #	Serial #	Cable Description		Repair Part Number	Quantity	Cost	Inspection Fee \$100 Per Hour	Total Repair Cost
		description of approximate length of cable desired, what the damage is, how the damaged area is marked, and work expected to be done)	Repair Description					
10	(\$		\$
11						\$		\$
12	(\$		\$
13						\$		\$
14						\$		\$
15						\$		\$
16						\$		\$
17						\$		\$
18						\$		\$
19						\$		\$
20						\$		\$